Williams Visit Report

School: Korematsu Middle School

Visit Date: 9/15/2017

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Document Review:

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- **4.** Science: sufficient
- 5. ELD sufficient
- 6. Foreign Language sufficient

Visitation:

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- **4.** Science: sufficient
- 5. ELD sufficient
- 6. Foreign Language sufficient

Overall Facilities Rating: GOOD 97.20% Outstanding facilities/warm culture! Thank you for a wonderful visit!

Facility issues which affect the overall rating: Interior Surfaces

- a. Gym wall panel system and related trim is separating from the walls/failing
- b. Gym lobby wall panel system and related trim is separating from the walls/failing
- c. Room A205 clutter (table tipped on side)
- 2. Restrooms
 - a. Room A205 clutter in shower
- 3. Fire Safety
 - a. Gym lobby fire extinguisher cabinet damaged
- 4. Roofs
 - a. General: roof weeds
- 5. Playgrounds / school grounds:

Williams Visit Report

- a. Landscaped areas and general grounds Excellent!
- b. Bldg. D weeds

6. Windows/doors

- a. Bldg A (exterior) door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- b. Bldg B door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- c. Bldg C door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- d. Library door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- e. Bldg D door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- f. Gym door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable
- g. Cafeteria door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable; broken windows (x3)
- h. Gym lobby door hardware inop; hardware secured and/or mounted incorrectly causing latching to be inoperable