# Williams Visit Report

School: Fremont Elementary School

Visit Date: 8/18/2017

Uniform Complaint Policies: In Compliance

**SARC:** In Compliance

### **Textbooks:**

## Visitation:

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- **4.** Science: sufficient
- 5. ELD sufficient

#### **Document Review:**

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- 4. Science: sufficient
- 5. ELD sufficient

Facilities Rating: Fair 88.87%

Happy kids, friendly staff, older school... well kept, but in fair repair.

### Facility Issues that affect the overall rating:

- 1. Interior Surfaces
  - a. Kindergarten bldg.'s K1,2,37) overhead storage, damaged ceiling tiles
  - b. C-wing boys' restroom damaged tiles, missing sensor covers (repairs in progress)
  - c. C-wing girls' restroom– damaged tiles, missing sensor covers (repairs in progress)
  - d. D-wing boys' restroom damaged tiles, missing sensor covers (repairs in progress)
  - e. D-wing girls' restroom– damaged tiles, missing sensor covers (repairs in progress)
  - f. Room 3 damaged baseboard(s), flooring tiles
  - g. Room 7 overhead storage

# Williams Visit Report

- h. Room 9 overhead storage
- i. Room 16 overhead storage; damaged flooring tile(s)
- j. Room 23 inop pencil sharpener
- k. Room 24 overhead storage
- 2. Overall Cleanliness
  - a. Bldg. 2 (7-10) housekeeping (shopping cart?)
  - b. B-wing girls' restroom restroom cleanliness
  - c. Room 3 housekeeping issues
- 3. Electrical
  - a. Computer lab exposed wires
  - b. Room 3 cord management
- 4. Restrooms
  - a. B-wing girls' restroom damaged seat covers
- 5. Sinks and Fountains
  - a. Room 7 unsecured water fountain lid(s)
- 6. Playgrounds / school grounds
  - a. Courtyard tree stumps IFP Room 19
  - b. Primary playground inop slide; paint in disrepair
  - c. Intermediate playground exposed pipes, missing basketball nets, paint in disrepair
  - d. Portable 28 Damaged concrete with exposed metal