

# Williams Visit Report

**School:** Mission Elementary School

**Visit Date:** 8/17/2017

**Uniform Complaint Policies:** In Compliance

**SARC:** In Compliance

**Textbooks:**

**Visitation:**

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies – sufficient
4. Science: - sufficient
5. ELD – sufficient

**Document Review:**

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

**Facilities Rating: GOOD 94.42%**

**Beautiful school and grounds!**

**Facility Issues that affect the overall rating:**

1. Mechanical / HVAC
  - a. A-wing boys' restroom – inop exhaust fan
2. Interior Surfaces
  - a. Cafeteria – damaged treading
  - b. Library -- damaged paint
  - c. A-wing girls' restroom – damaged ceiling tile (s)
  - d. B-wing boys' restroom – damaged paint
  - e. B-wing girls' restroom – crack in wall(s)
3. Electrical
  - a. Library – inop lights
4. Sinks and Fountains
  - a. A-wing bldg.. – inop water fountain
  - b. B-wing boys' restroom – inop sink (work order in place)
5. Structural damage
  - a. Portables – failing porch decking

## Williams Visit Report

6. Playgrounds / school grounds
  - a. Play structures (low tanbark)
  - b. Asphalt playgrounds – standing water under solar panel; crack IFO B4
7. Windows/doors
  - a. Portables – paint damage on doors