

Williams Visit Report

School: Oak Grove Middle School

Visit Date: 9/1/2017

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Document Review:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD – sufficient
6. Foreign Language – sufficient

Visitation:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient
6. Foreign Language – sufficient

Overall Facilities Rating: FAIR 87.63%

Friendly staff and students. Some classrooms really well organized and attractive!

Facility issues which affect the overall rating:

1. Mechanical / HVAC
 - a. G-Bldg. (exterior) – skirt vent detached outside G2
 - b. A5 – damaged vent grates (sharp edges)
 - c. D3 – damaged vent grates (sharp edges)
2. Interior Surfaces
 - a. Gym interior – damaged locker(s) (bolts)
 - b. A2 – cracked counter top, damaged ceiling tiles
 - c. A4 – damaged ceiling tiles, unsecured cabinet(s)
 - d. A5 - damaged flooring tiles, damaged ceiling tiles
 - e. A8 - damaged ceiling tiles
 - f. B5 - overhead storage

Williams Visit Report

- g. C5 - overhead storage
 - h. D3- overhead storage
 - i. D7 – cracks in wall
 - j. D8- overhead storage
 - k. D9- overhead storage; damaged ceiling tiles
 - l. E1 – unsecured mirror
 - m. E3 - damaged ceiling tiles
 - n. F2 - damaged ceiling tiles
 - o. F8- overhead storage
3. Overall Cleanliness
 - a. A4 – dusty
 4. Pest/Vermin Infestation
 - a. A-wing - pest smell in many classrooms
 5. Electrical
 - a. Gym interior – inop light(s)
 - b. D9 – cord management
 - c. E3 – exposed wires
 - d. F5 - inop light(s)
 - e. F8 - inop light(s)
 6. Restrooms
 - a. D-wing Boys’ restroom – damaged paper towel dispenser
 - b. Cafeteria Girls’ restroom - damaged paper towel dispenser
 7. Sinks and Fountains
 - a. A-wing (exterior) – inop fountains
 - b. A3 – inop water fountain
 - c. A8 – rusted sink, sharp edges
 - d. C5 – rusted, exposed pipe under sink(s)
 8. Fire Safety
 - a. A5 – missing fire extinguisher
 9. Hazardous Materials
 - a. A5 – hazardous materials under sink (s)
 - b. C5 – hazardous materials under sink (s)
 - c. D8 – extreme clutter/fire hazard
 10. Structural damage
 - a. Gym bldg. (exterior) – paint in disrepair
 - b. E-Bldg. (exterior) – dry rot trim outside of E3-4-5
 - c. A3 – chipped exterior paint
 - d. D-wing (exterior) –ceiling stucco crumbling
 11. Roofs
 - a. A-wing (exterior) – damaged drainpipe, damaged roofing, stucco crumbling, gutters eroding
 - b. B-wing (exterior) – damaged roofing, stucco crumbling, gutters eroding
 12. Playgrounds / school grounds

Williams Visit Report

- a. Grass sports field – gophers (unsafe/not usable)
- b. General grounds – unkempt landscaping