Williams Visit Report

School: Hercules Middle School

Visit Date: 9/15/2017

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Document Review:

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- 4. Science: sufficient
- 5. ELD sufficient

Visitation:

- 1. ELA sufficient
- 2. Math: sufficient
- 3. Social Studies sufficient
- 4. Science: sufficient
- 5. ELD sufficient

Overall Facilities Rating: GOOD 95.59%

Clean yard and organized classrooms; calm feeling all around campus! Staff was accommodating and friendly! Use of technology/tablets was interesting!

Facility issues which affect the overall rating:

- 1. Interior Surfaces
 - a. Boys' locker room 407 bldg. entry mats in disrepair; damaged privacy panels; wall tile damage
 - b. Girls' locker room 410 bldg. entry mats in disrepair; unkempt
- 2. Electrical
 - a. Library inop light(s)
 - b. Boys' locker room 407 bldg. inop light(s)
 - c. Girls' locker room 410 bldg. inop light(s)
- 3. Sinks and Fountains
 - a. Boys' locker room 407 bldg. inop drinking fountain
- 4. Fire Safety
 - a. Locker facility panic hardware inop

Williams Visit Report

5. Structural damage

- a. 100 buildings (exterior) paint in disrepair at most upper structural roof extensions
- b. 200 buildings MPR (exterior) paint in disrepair at most upper structural roof extensions
- c. 300 buildings (exterior) paint in disrepair at most upper structural roof extensions
- d. 400 buildings Gym (exterior) paint in disrepair at most upper structural roof extensions
- e. 500 portables 501-509 (exterior) damaged siding and window frames at 502, 503, 506

6. Roofs

- a. 100 buildings (exterior) missing/damaged screens; windows unkempt (dust and debris build-up)
- b. 200 buildings MPR (exterior) missing/damaged screens; windows unkempt (dust and debris build-up)
- c. 300 buildings (exterior) missing/damaged screens; windows unkempt (dust and debris build-up)
- d. 400 buildings Gym (exterior) missing/damaged screens; windows unkempt (dust and debris build-up)
- e. Gym ceiling reflects roof leak

7. Windows/doors

- a. Boys' locker room 407 bldg. missing door-stop/damage
- b. Girls' locker room 410 bldg. damaged/missing window screen(s); doors/windows unkempt (PSL*)
- c. 500 portables 510-516 (exterior) damaged/missing window screen(s); doors/windows unkempt (PSL*)

*PSL = Poor Service Levels