

Williams Visit Report

School: Lake Elementary School

Visit Date: 9/18/2017

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Document Review:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

Visitation:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

Overall Facilities Rating: FAIR 88.31%

Clean interiors, beautiful hall displays! Friendly and courteous students and staff! (Wishlist: extra office space for therapists and storage!)

Facility issues which affect the overall rating:

1. Interior Surfaces
 - a. Boys' restrooms IFO POD – loose floorboard(s), missing mirrors
 - b. Girls' restrooms IFO POD – missing seat covers
 - c. POD center – benches in disrepair (paint)
 - d. Room 7 – damaged blinds
 - e. Room 8 – damaged tiles
2. Overall Cleanliness
 - a. MPR (exterior) – building hygiene (spider webs)
 - b. Portables 15-16 (exterior) - building hygiene (spider webs)
3. Electrical
 - a. Room 7 – motion detector hanging from ceiling
 - b. Room 21 – missing light cover(s); loose light cover(s)
 - c. Room 23 – loose light cover(s)
4. Restrooms

Williams Visit Report

- a. Boys' restrooms IFO POD – no soap
 - b. Boys' restrooms IBO POD – missing indication light
 - c. Girls' restrooms IBO POD – missing indication light
5. Sinks and Fountains
- a. Boys' restrooms Bldg. B – inop faucet(s)
 - b. Girls' restrooms Bldg. B – inop faucet(s)
 - c. Boys' restrooms IFO POD – inop faucet(s)
 - d. General grounds – rusted water fountain
 - e. Room 8 – loose drinking fountain
6. Hazardous Materials
- a. Room 3 –chemicals under sink
7. Playgrounds / school grounds
- a. Playground structure – playground hygiene (debris in tanbark, litter on field, peeling surfaces. LO field overgrown
 - b. General grounds – broken/damaged bench(es)
 - c. Asphalt areas – cracks near basketball court(s) and MPR
8. Windows/doors
- a. Computer lab – emergency door missing indication sign
 - b. Cafeteria – damaged door frame
 - c. Room 3 – door: hole(s), rusted nail(s)