

Williams Visit Report

School: Lincoln Elementary School

Visit Date: 9/14/2017

Uniform Complaint Policies: In Compliance

SARC: In Compliance

Textbooks:

Document Review:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

Visitation:

1. ELA - sufficient
2. Math: - sufficient
3. Social Studies - sufficient
4. Science: - sufficient
5. ELD - sufficient

Overall Facilities Rating: GOOD 90.78%

**Warm and friendly environment. Ready and cooperative staff and principal.
New solar panels on playground!**

Facility issues which affect the overall rating:

1. Interior Surfaces
 - a. Stairwell IFO office – paint on railing in disrepair
 - b. Upper hallways and corridors - paint on railing in disrepair
 - c. Room 112 – overhead storage (several classrooms)
 - d. Room 122 – overhead storage (several classrooms)
 - e. Room B203 – overhead storage (several classrooms)
 - f. Room B209 – overhead storage (several classrooms)
2. Electrical
 - a. Cafeteria – inop light(s)
 - b. Boys' restroom – inop light(s) (fixed)
3. Playgrounds / school grounds
 - a. Kindergarten play structure – rubber mats in disrepair (tripping hazard)
 - b. Kindergarten playground – damaged/worn out foam vinyl tile(s)

Williams Visit Report

- c. Main play structure – paint in disrepair, damaged/missing foam mat(s)
- d. Main playgrounds – damaged asphalt, uneven surfaces (tripping hazards)
- e. Main playgrounds – damaged asphalt, uneven surfaces (tripping hazards)
- f. General grounds – damaged asphalt, uneven surfaces (tripping hazards); missing mulch/ground cover